




Damaged Suspect Asbestos Material.



Old Knob And Tube Wiring.



Severely Corroded Water Shut Off Valve.



Torn / Damaged Roof Shingle.



Termite Shelter Tubes And Termite Damage To Floor Joist.



Evidence Of Past Water Presence In Basement.